WELL COMPLETION REPORT

LAKE CARHEL

PUTNAM COUNTY DEPARTMENT OF HEALTH

Division of Environmental Health Services
COUNTY OFFICE BUILDING - CARMEL, NEW YORK

This report is to be completed by well driller and submitted to County Health Department together with laboratory report of analysis of water sample indicating water is of satisfactory bacterial quality before certificate of construction compliance is issued.

REPORT MUST BE SUBMITTED WITHIN 30 DAYS OF WELL COMPLETION

P901

OWNER	NAM!				ADDRESS		E 63 - E	en contrave
LOCATIO	997	Toni Monteleone			Cherry Hill Road, Carmel, New York			
OF WEL		Cherry Hill Road			Carmel, New York			(Lot Number)
PROPOSE USE OF WELL	ПР	OMESTIC UBLIC UPPLY	BUSINESS ESTABLISHME INDUSTRIAL	NT	FARM	Avra (e	TEST WELL	470 5
DRILLING		OTARY COMPRESSED AIR PERCUSSION			CONDITIONING (Specify) CABLE OTHER (Specify)			
CASING LENGTH (reet) DETAILS 34			DIAMETER (Inches) WEIGHT PER FOOT		THREADED WELDED		DRIVE SHOE	WAS CASING GEOUTED?
YIELD	Пв	AILED	PUMPED	COMPRES	SED AIR	HOURS	G.P.M.	YIELD (G.P.M.)
WATER	-	MEASURE FROM LAND SURFACE - STATIC (Specify feet) DURIN				4	Depth of Completes	
	MAKE	MAKE			+=0.0		in feet below Land	LENGTH OPEN TO AQUIPER (100
SCREEN		SIZE	DIAMETER (inches)	IF GRAVEL	Diameter of		GRAVEL SIZE (Inches)	FROM (feet) TO (feet)
PTH FEOM	LAND SURFACE			PACKED:	gravel pack			
1220 - 50 - 600-0	o FEET	FORMATION DESCRIPTION			Sketch exact location of well with distances, to at least two permanent landmarks.			
0	4	Soft Clay & Boulders					.50	7
4	450	Hard Black & White Gran						
						-Nell		
						Dwell	ing	
If y	ield was test	ed at differen	I depths during drilling	z, list below				
FEET GALLONS PER MINUTE								
270 -			3/4					
			1-1/2					S D S
	320							Ca.
	320 400		2-	1/2				3-
			2		777	CIERRY	HILL RO	âD